

# *Inspection Photos*

*Loc#335690*

*Operator: Caerus*

*Inspection Number: 692400076*

*Inspection Date: 8/22/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to Southeast.

August 22, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus UWF KO4 Loc#335690



Photo#2:  
Overview of Interim Reclamation area.

August 22, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus UWF K04 Loc#335690



**Photo#3:**

One area of developing concern at SE corner of Pad where water drains to Sediment trap.

August 22, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus UWF K04 Loc#335690