

Inspection Photos

Loc#311674

Operator: Caerus

Inspection Number: 692400079

Inspection Date: 8/22/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southwest.

August 22, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus NP Loc#311674



Photo#2:
Overview of Interim Reclamation area on North side of Location.

August 22, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus NP Loc#311674



Photo#3:
Materials stockpile is stored on West end of Location.

August 22, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus NP Loc#311674



Photo#4:

Sediment is migrating from East side of Access road ditch across location in shallow swale ditch that crosses entry & off into Interim Reclamation area.

August 22, 2018



Photo#5:



Photo#6:

Sediment is migrating from East side of Access road ditch across location in shallow swale ditch that crosses entry & off into Interim Reclamation area.

August 22, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus NP Loc#311674