

Construction and Stormwater Inspection

August 31, 2018

Operator: SRC ENERGY INC- #10311

Location ID: 454405

Inspection Document #: 682403954

Weld County, CO

NESE Section 1 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Bluff Federal State /40-1
Pad
Location ID: 454405



Photo 1. Photo taken from the northeast perimeter of the location, facing West. Ditch and berm BMP has been installed around the entire perimeter of the location. Culverts are needed and were staged on location.



Photo 2. Photo taken from the northwestern perimeter of the location, facing West. Photo illustrates where a culvert is needed in conjunction with the ditch and berm BMP.

Inspection Photos
Location Name: Bluff Federal State /40-1
Pad
Location ID: 454405



Photo 3. Photo taken from the northwest perimeter of the location, facing Southwest. Sediment trap is IN-PROCESS of being constructed. Sediment trap lacks both inlet and outlet protection devices.



Photo 4. Photo taken from the northwestern perimeter of the location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: Bluff Federal State /40-1
Pad
Location ID: 454405



Photo 5. Photo taken from the southeastern perimeter of the location, facing North. Topsoil has been salvaged and stored along the western and eastern perimeter of the location. Topsoil has been seeded, straw mulched and crimped.



Photo 6. Photo taken from the northeastern perimeter of the location, facing North. See comments under Photo 5.