

Interim Reclamation and Stormwater Inspection

August 31, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP- #47120

Location ID: 302901

Inspection Document #: 682403956

Weld County, CO

NWNW Section 4 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: PAVISTMA #4-22
Location ID: 302901



Photo 1. Photo taken of the Operator sign at the battery location.



Photo 2. Photo taken of the northern battery location, facing North. Berm BMP in need of repair. Sediment discharge was observed off location.

Inspection Photos
Location Name: PAVISTMA #4-22
Location ID: 302901



Photo 3. Photo taken from the northern entrance to the battery location, facing West. Kochia and Musk thistle weeds observed along portions of the battery location.



Photo 4. Photo taken from the western battery location, facing South. Photo illustrates Kochia and Musk thistle. See comments under Photo 1.