

Inspection Photos
Operator: GRAND MESA OPERATING CO - 35080
Location ID: 456610




Photo 12: 2017 Google Earth aerial imagery. 2A doc. #401665224 states size of disturbance area during construction will be 2.5 acres in size. GPS measurements were conducted indicating that the disturbance area, not including the fence line, is 3.14 acres in size.

