

Inspection Photos

Operator: BP America

API: 05-067-07037

Date: 8/16/2018



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern portion of the project area from the southeastern corner facing westward.



Photo 3. View of the eastern portion of the project area from the southeastern corner facing northward.



Photo 4. View of vegetation that appears dead within the southern project area.



Photo 5. View of large kochia (*Kochia scoparia*) plants that will soon dry and become debris.