

Inspection Photos - FIRE  
Location Name: Gregory 0780 1-09H  
Location ID: 439603



**Photo 1. Overview of area of location impacted by equipment fire.**



**Photo 2. Close-up overview of area impacted by equipment fire. (1 of 3)**

Inspection Photos - FIRE  
Location Name: Gregory 0780 1-09H  
Location ID: 439603



**Photo 3. Close-up overview of area impacted by equipment fire. (2 of 3)**



**Photo 4. Close-up overview of area impacted by equipment fire. (3 of 3)**

Inspection Photos - FIRE  
Location Name: Gregory 0780 1-09H  
Location ID: 439603



**Photo 5. Close-up overview of jet pump 1 of 4.**



**Photo 6. Close-up overview of jet pump 1 of 4.**



Inspection Photos - FIRE  
Location Name: Gregory 0780 1-09H  
Location ID: 439603



**Photo 7. Close-up overview of jet pump 1 of 4.**



**Photo 8. Close-up overview of area between jet pump 1 of 4 and separator 1 of 3.**

Inspection Photos - FIRE  
Location Name: Gregory 0780 1-09H  
Location ID: 439603



**Photo 9. Close-up overview of fluids and debris present in berm of separator 1 of 3.**



**Photo 10. Close-up overview of fluids and debris present in berm of separator 1 of 3.**

Inspection Photos - FIRE  
Location Name: Gregory 0780 1-09H  
Location ID: 439603



**Photo 11. Close-up overview of jet pump housing for pump 2 of 4.**



**Photo 12. Close-up overview of jet pump 2 of 4.**



Inspection Photos - FIRE  
Location Name: Gregory 0780 1-09H  
Location ID: 439603



**Photo 13. Close-up overview of jet pump 2 of 4 and separator 1 of 3 from corner of fire area. Stained soil visible.**



**Photo 14. Close-up overview of jet pump 2 of 4.**

Inspection Photos - FIRE  
Location Name: Gregory 0780 1-09H  
Location ID: 439603



**Photo 15. Close-up overview of area between jet pump 2 of 4 and separator 2 of 3, taken standing in front of jet pump 2 of 4. Stained soil and free fluid visible.**



**Photo 16. Close-up overview of jet pump 3 of 4 and separator 2 of 3, taken standing in front of jet pump 2 of 4. Stained soil visible.**



Inspection Photos - FIRE  
Location Name: Gregory 0780 1-09H  
Location ID: 439603



**Photo 17. Close-up overview of jet pump 3 of 4.**



**Photo 18. Close-up overview of jet pump 4 of 4 and separator 3 of 3. Stained soil visible.**

Inspection Photos - FIRE  
Location Name: Gregory 0780 1-09H  
Location ID: 439603



**Photo 19. Close-up overview of jet pump 4 of 4.**



**Photo 20. Close-up overview of jet pump 4 of 4.  
Stained soil and broken glass visible.**