

Inspection Photos

Operator: Logos Operating

API: 05-067-06805

Date: 8/16/2018



Photo 1. View of the project area from the southeastern edge facing center. Revegetation is progressing within the southern project area.



Photo 2. View of the eastern corner of the project area from the northwestern corner facing southward.



Photo 3. View of the northern portion of the project area from the northeastern corner facing westward.



Photo 4. View of the eastern project area from the northeastern edge facing southward.