

Inspection Photos

Loc#335522

Operator: Terra

Inspection Number: 692400106

Inspection Date: 8/31/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location from entry to Southwest. Insert is Debris weeds that have been scraped to edge of Location.

August 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Jolley KPLoc#335522



Photo#2:
Areas that should be in Interim Rec are hard-packed, graveled and weedy.

August 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Jolley KPLoc#335522



Photo#3:

Perennial vegetation in areas of Interim Reclamation appears sparse & infested with annual weeds.

Photo#4:

August 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Jolley KPLoc#335522