

Inspection Photos

Location Name: Chevron-65S97W 26SESE Pad
Location ID: #383259 Spill/Release ID: #456951
Inspection Date: August 29, 2018



Photo #1 – Facility sign located at entrance to pad.



Photo #2 – Wellhead with sign.



Inspection Photos

Location Name: Chevron-65S97W 26SESE Pad
Location ID: #383259 Spill/Release ID: #456951
Inspection Date: August 29, 2018



Photo #3 – View of pit from NE.



Photo #4 – Soil stockpiles west of pit (1).



Inspection Photos

Location Name: Chevron-65S97W 26SESE Pad
Location ID: #383259 Spill/Release ID: #456951
Inspection Date: August 29, 2018



Photo #5 - Soil stockpiles west of pit (2).



Photo #6 – Small stockpiles of soil north of separator.



Inspection Photos

Location Name: Chevron-65S97W 26SESE Pad
Location ID: #383259 Spill/Release ID: #456951
Inspection Date: August 29, 2018



Photo #7 – Operator’s representatives were in the process of removing tanks on inspection date.



Photo #8 – Equipment associated with tanks (stairway, loadout container, panel fence) stored at south end of pad.



Inspection Photos

Location Name: Chevron-65S97W 26SESE Pad
Location ID: #383259 Spill/Release ID: #456951
Inspection Date: August 29, 2018



**Photo #9 – Looking into tank battery berm from NE corner.
No visible impacts from condensate release were observed.**



Photo #10 – No visible impacts were observed immediately downhill (looking southeast) from tank battery.

