

Inspection Photos
Location Name: Dowdell 1
API: 05-057-06252



Photo 1. Overview of location facing southwest.



Photo 2. Photo of area where pits used to be.

Inspection Photos
Location Name: Dowdell 1
API: 05-057-06252



Photo 3. Photo of area where pits used to be.



Photo 4. Tank with no berm and no label.