

Inspection Photos
Location Name: A. P. Urie 2
API: 05-081-05288



Photo 1. Overview of location taken at entrance facing west.

Inspection Photos
Location Name: A.P. Urie 2
API: 05-081-05288



Photo 2. Unmarked risers.



Photo 3. Stained soil at wellhead. Chemical drums without secondary containment.