

Final Reclamation Inspection

September 5, 2018

Operator: TOP OPERATING COMPANY - 39560

API: 05-123-09795

Inspection Document #: 682403972

Weld County, CO

SESE Section 25 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: VALARIE G. HITCHINGS #1
API: 05-123-09795



Photo 1. Photo taken from the southern location on June 27, 2016, facing North. Equipment and debris (i.e. railroad ties) needs to be removed per Rule 1004.



Photo 2. Photo taken from the southern location on September 5, 2018, facing North. See comments under Photo 1.

Inspection Photos
Location Name: VALARIE G. HITCHINGS #1
API: 05-123-09795



Photo 3. Close up photo taken on June 27, 2016, facing West. Equipment and debris needs to be removed per Rule 1004.



Photo 4. Close up photo taken on September 5, 2018, facing West. See comments under Photo 3.