

Inspection Photos  
Location Name: MARTIN T. HART D 1  
Facility ID: 240154



Photo 1. Wellhead



Photo 2. Tank battery/Unmarked unplugged riser