

**Inspection Photos**  
**Location Name: MARTIN T. HART UNIT G #1**  
**Facility ID: 240922**



**Photo 1. Wellhead**



**Photo 2. Tank battery/Unmarked unplugged riser**

**Inspection Photos**  
**Location Name: MARTIN T. HART UNIT G #1**  
**Facility ID: 240922**



**Photo 3. stained soil**



**Photo 4. Stained soil**

**Inspection Photos**  
**Location Name: MARTIN T. HART UNIT G #1**  
**Facility ID: 240922**



**Photo 5. Stained soil**



**Photo 6. Stained soil/trash**

Inspection Photos  
Location Name: MARTIN T. HART UNIT G #1  
Facility ID: 240922



**Photo 7. Stained soil**



**Photo 8. Unmarked riser**

Inspection Photos  
Location Name: MARTIN T. HART UNIT G #1  
Facility ID: 240922



Photo 9. Stained soil



Photo 10. Stained soil/trash