

## Inspection Photos

Location Name: Sandridge Energy Poudre Canyon Spill, Spill ID 456513

Inspection Date: 9/5/2018



Photo 1 – Excavated spill area from downslope, eastern end of spill looking northwest (upcanyon).



Photo 2 –Excavated spill area and termination of spill extent, looking southeast (down canyon).



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Sandridge Energy Poudre Canyon Spill, Spill ID 456513

Inspection Date: 9/5/2018



Photo 3 – Viewing excavated spill area, looking northwest (up canyon).



Photo 4 –From near crash and spill point of origin, looking southeast (down canyon).



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Sandridge Exploration and Production Poudre Canyon Spill, Spill ID 456513

Inspection Date: 9/5/2018



Photo 5 – Stockpiled excavated material staged for disposal.



Photo 6 –Crash site and spill source area. Area scraped to existing asphalt surface.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Sandridge Energy Poudre Canyon Spill, Spill ID 456513

Inspection Date: 9/5/2018



Photo 7 – Operator sample location 02 within excavated spill area. COGCC jars of sample collected adjacent Operator sample location.




Photo 8 –Photo of Operator's 8/7/2018 background soil sample location in pull off on south side of Highway 14 west of Hewlett Gulch.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources