

Inspection Photos

Location Name: Weideman 20-20 Location ID 305243, Spill ID 444663, REM 9687

Inspection Date: 9/5/2018



Photo 1 – SVE/AS trailer



Photo 2 –Spill source area/former condensate AST location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Weideman 20-20 Location ID 305243, Spill ID 444663, REM 9687

Inspection Date: 9/5/2018



Photo 3 – Damaged monitoring well on east side of source area/adjacent ditch.



Photo 4 – Rill forming from stormwater runoff. Stormwater controls require maintenance.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources