

# Inspection Photos

09/05/2018

Operator: DIVERSIFIED OPERATING  
CORPORATION - 24461

Location ID: 331849

Inspection Doc. Number: 682503858  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: DIVERSIFIED OPERATING CORPORATION - 24461  
Location ID: 331849



**Photo 1:** Photo taken from the south end of the location, facing west. Previous inspections required operator to perform reclamation on access road and location. Photo shows no reclamation activities appear to have been conducted.

Inspection Photos  
Operator: DIVERSIFIED OPERATING CORPORATION - 24461  
Location ID: 331849



**Photo 2:** Photo taken from the south end of the location, facing north. Previous inspections required operator to perform reclamation on access road and location. Photo shows no reclamation activities appear to have been conducted.



**Photo 3:** Photo taken from the south end of the location. Photo shows Diffuse Knapweed (arrow) found on the location. Plant appears to have matured and is currently seeding out.



**Photo 4:** Photo taken from the south end of the location. Photo shows Diffuse Knapweed (arrow) found on the location. Plant appears to have matured and has seeded out



**Photo 5:** Photo taken from access road. Photo shows Diffuse Knapweed (arrow) found on the access road. Plant appears to have matured and is currently seeding out.



**Photo 6:** Photo taken from access road. Photo shows Diffuse Knapweed (arrow) found on the access road. Plant appears to have matured and is currently seeding out.



**Photo 7:** Photo taken from the access road. Photo shows cattle guard and access road has not been reclaimed.