

Inspection Photos

09/05/2018

Operator: FOUNDATION ENERGY
MANAGEMENT LLC - 10112

Location ID: 330509

Inspection Doc. Number: 682503864
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the access road, north of the location facing south. Photo shows Diffuse Knapweed has not been sufficiently managed or removed from access road.



Photo 2: Photo taken from the access road. Photo shows Diffuse Knapweed has not been sufficiently managed or removed from access road.

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 330509



Photo 3: : Photo taken from the access road, facing south. Photo shows Diffuse Knapweed has not been sufficiently managed or removed from access road.



Photo 4: Photo taken from the northwest end of the location, facing south. Photo shows Diffuse Knapweed has not been sufficiently managed or removed from location.



Photo 5: Photo taken from the northeast end of the location, facing southeast. Photo shows Diffuse Knapweed has not been sufficiently managed or removed from location.



Photo 6: Photo taken from the southeast end of the location, facing south. Photo shows Diffuse Knapweed has not been sufficiently managed or removed from location.



Photo 7: Photo taken from the southwest end of the location, facing north. Photo shows Diffuse Knapweed has not been sufficiently managed or removed from location.