

# Inspection Photos

09/05/2018

Operator: FOUNDATION ENERGY  
MANAGEMENT LLC - 10112

Location ID: 331346

Inspection Doc. Number: 682503874  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112  
Location ID: 331346



**Photo 1:** Photo taken from the north end of the battery location, facing east. Photos 1-4 provide an overview of the former battery/pit location from east, to south, to west. Photos show additional reclamation activities, and activities required per the corrective action, appear to have been conducted.



**Photo 2:**

Inspection Photos  
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112  
Location ID: 331346



Photo 3:



Photo 4:

Inspection Photos  
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112  
Location ID: 331346



**Photo 5:** Photo taken from the south end of the former battery location, facing south. Photo shows additional reclamation activities appear to have been conducted along access road.



**Photo 6:** Photo taken from the north end of the well location, facing east. Photos 6-8 provide an overview of the former well location from east, to south, to west. Photos show additional reclamation activities appear to have been conducted.

Inspection Photos  
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112  
Location ID: 331346



Photo 7:



Photo 8: