

Inspection Photos

Operator: Logos Operating

API: 05-067-05520

Date: 9/10/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 3. View of the western project area from the southwestern edge facing northward. Pipes need to be properly stored off of the well pad.