

Final Reclamation Inspection

September 10, 2018

Operator: TOP OPERATING COMPANY - 39560

API: 05-123-10818

Inspection Document #: 682403976

Weld County, CO

SWSE Section 25 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: EWING #2
API: 05-123-10818



Photo 1. Photo taken east of the well location, facing South. Operator has failed to remove unused equipment after previous corrective actions have been issued.

Inspection Photos
Location Name: EWING #2
API: 05-123-10818



Photo 2. Photo taken from the well location on August 20, 2015. Operator has failed to remove unused equipment after corrective actions have been issued.

Inspection Photos
Location Name: EWING #2
API: 05-123-10818



Photo 3. Photo taken east of the well location, facing West. Well location has undergone a land use change to gravel mining.