

Inspection Photos

Loc#335304

Operator: Terra

Inspection Number: 692400116

Inspection Date: 8/28/2018





Photo#1:
Overview of Location from entry to North.

August 28, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Clough Loc#335304



Photo#2: 8/14/18
Perimeter Wattles were not properly installed.



Photo#3: 8/28/18
Wattles have been properly installed

August 28, 2018



Photo#4:
Other BMPs installed.

August 28, 2018



Photo#5:



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Clough Loc#335304