

Location Name: Beren Corporation – Brewer A Tank Battery
Inspection Date: 8/13/2018



Photo # - 1



Location Name: Beren Corporation – Brewer A Tank Battery
Inspection Date: 8/13/2018



Photo # - 2

View east along southern wall of north pit excavation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Beren Corporation – Brewer A Tank Battery
Inspection Date: 8/13/2018



Photo # - 3

View east along northern wall of north pit excavation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Beren Corporation – Brewer A Tank Battery
Inspection Date: 8/13/2018



Photo # - 4

View southeast across north pit excavation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Beren Corporation – Brewer A Tank Battery
Inspection Date: 8/13/2018



Photo # - 5

View south along east wall of the north pit excavation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Beren Corporation – Brewer A Tank Battery
Inspection Date: 8/13/2018



Photo # - 6

View southwest across the north pit excavation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Beren Corporation – Brewer A Tank Battery
Inspection Date: 8/13/2018



Photo # - 7

View west across the north pit excavation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Beren Corporation – Brewer A Tank Battery
Inspection Date: 8/13/2018



Photo # - 8

View west across the north pit excavation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Beren Corporation – Brewer A Tank Battery
Inspection Date: 8/13/2018



Photo # - 9

View west across the north pit excavation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Beren Corporation – Brewer A Tank Battery
Inspection Date: 8/13/2018



Photo # - 10

View north across the north pit excavation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Beren Corporation – Brewer A Tank Battery
Inspection Date: 8/13/2018



Photo # - 11

View south across the south pit excavation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources