

Construction and Stormwater Inspection

September 5, 2018

Operator: NOBLE ENERGY INC- #100322

Location ID: 456625

Inspection Document #: 682403980

Weld County, CO

NENW Section 19 T3N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: D /19-03 Pad
Location ID: 456625



Photo 1. Photo taken from the northeastern location, facing South. Surface roughening BMP installed around portions of the perimeter location. This location is very sandy and will require more appropriate BMPs than surface roughening. Operator indicated that the entire disturbance area would be hydromulched and seeded upon completing the pad construction. Photo also illustrates the topsoil stockpile that has been temporarily stabilized with equipment tracking.

Inspection Photos
Location Name: D /19-03 Pad
Location ID: 456625



Photo 2. Photo taken from the southeastern location, facing West. Appears a retention pond has been constructed. Operator indicated pad will be sloped (0.5%) towards the south to allow for proper drainage. See comments under Photo 1.

Inspection Photos
Location Name: D /19-03 Pad
Location ID: 456625



Photo 3. Photo taken from the southern location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: D /19-03 Pad
Location ID: 456625



Photo 4. Photo taken from the northwestern location, facing North. Operator is driving over the top of the BMP. Operator shall keep off BMPs so they remain in proper functioning condition. Operator indicated that surface roughening BMPs are re-rippped every 2 days due to vehicle and equipment traffic.

Inspection Photos
Location Name: D /19-03 Pad
Location ID: 456625



Photo 5. Photo taken from the western location, facing East. Operator is in-process of constructing the location.