

Inspection Photos

Operator: Mclane Trust* Dixie

API: 05-067-06049

Date: 9/10/2018



Photo 1. View of the project area from the eastern edge facing westward.



Photo 2. View of the northern portion of the project area from the eastern edge facing northwestward.



Photos 3-5. View of examples of small trash and debris on the well pad that need to be removed.