

Inspection Photos  
Location Name: Okes 5-6  
API: 05-081-06798



**Photo 1. Overview of location taken at entrance facing east.**

Inspection Photos  
Location Name: Okes 5-6  
API: 05-081-06798



**Photo 2. Incorrect emergency contact information on location signs.**



**Photo 3. Incorrect emergency contact information on location signs.**

Inspection Photos  
Location Name: Okes 5-6  
API: 05-081-06798



**Photo 4. Incorrect emergency contact information on location signs.**



**Photo 5. Hole in tank.**