

Location Name: Central Operating Inc. – Marick A 2 Battery (Rem #9799) Pit ID 117704
Inspection Date: 8/23/2018



Photo # - 1

Location Name: Central Operating Inc. – Marick A 2 Battery (Rem #9799) Pit ID 117704
Inspection Date: 8/23/2018



Photo # - 2

Location Name: Central Operating Inc. – Marick A 2 Battery (Rem #9799) Pit ID 117704
Inspection Date: 8/23/2018



Photo # - 3

Unused risers east of the separator



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Central Operating Inc. – Marick A 2 Battery (Rem #9799) Pit ID 117704
Inspection Date: 8/23/2018



Photo # - 4

View south at former oil skim pit excavation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Central Operating Inc. – Marick A 2 Battery (Rem #9799) Pit ID 117704
Inspection Date: 8/23/2018



Photo # - 5

View south at former oil skim pit excavation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Central Operating Inc. – Marick A 2 Battery (Rem #9799) Pit ID 117704
Inspection Date: 8/23/2018



Photo # - 6

View west at former oil skim pit excavation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Central Operating Inc. – Marick A 2 Battery (Rem #9799) Pit ID 117704
Inspection Date: 8/23/2018



Photo # - 7

View southwest at second production pit



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Central Operating Inc. – Marick A 2 Battery (Rem #9799) Pit ID 117704
Inspection Date: 8/23/2018



Photo # - 8

View north at impactation soil stockpile



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources