

Final Reclamation Inspection

September 5, 2018

Operator: NOBLE ENERGY INC- #100322

API: 05-123-30501

Inspection Document #: 682403992

Weld County, CO

SENE Section 24 T3N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: NOPENS H #24-08
API: 05-123-30501



Photo 1. Photo taken from the well location, facing North. The entire well location is dominated by Puncturevine which is not a desirable plant species. Little to no desirable vegetation was observed.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: NOPENS H #24-08
API: 05-123-30501



Photo 3. Photo taken along a portion of the well access road, facing South. Operator has failed to reclaim the access road per Rule 1004.a.

Inspection Photos
Location Name: NOPENS H #24-08
API: 05-123-30501



Photo 4. Reference photo taken northeast of the well location, facing South.