

# Final Reclamation Inspection

September 10, 2018

Operator: NOBLE ENERGY INC- #100322

API: 05-123-23921

Inspection Document #: 682404000

Weld County, CO

SESE Section 24 T6N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: DESHAZO #24-44  
API: 05-123-23921



**Photo 1.** Photo taken from the well location, facing North. Well location appears to meet Rule 1004 standards. A future assessment will be made along the well access road and tank battery location.