

Inspection Photos

09/12/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 430730

Inspection Doc. Number: 682503900

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 430730



Photo 1: Photo taken from the west end of the location, facing east. Photo shows PR well on site.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 430730



Photo 2: : Photo taken from the west end of the location, facing east. Photo shows overview of location.



Photo 3: Photo taken from the north end of the location, facing east. Photo shows vegetation over the reclamation area.