

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401762787  
Date Received:  
09/13/2018

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name:

Phone: ( ) Fax: ( )

Email:

Additional Operator Contact:

Contact Name	Phone	Email
Tesla Dougherty	970-304-5245	tesla.dougherty@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682503615

Inspection Date: 07/17/2018

FIR Submit Date: 07/18/2018

FIR Status:

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 327240

Location Name: MD RADKE-63N65W Number: 22SWNW County:

Qtrqr: SWN Sec: 22 Twp: 3N Range: 65W Meridian: 6  
W

Latitude: 40.212542 Longitude: -104.657101

FACILITY - API Number: 05-123-00 Facility ID: 327240

Facility Name: MD RADKE-63N65W Number: 22SWNW

Qtrqr: SWN Sec: 22 Twp: 3N Range: 65W Meridian: 6  
W

Latitude: 40.212542 Longitude: -104.657101

CORRECTIVE ACTIONS:

1  CA# 117528

Corrective Action: Remove riser(s) at battery facility in accordance to the 2017 Flowline NTO and requirements per reclamation rule 1004.a. Original CA date remains in place.

Date: 06/30/2017

Response: CA COMPLETED

Date of Completion: 08/20/2018

Operator Comment: Risers have been removed from location.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

Previous inspections documented 2 (two) risers remaining on location. Operator submitted photo documentation of only 1 riser being removed.

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: \_\_\_\_\_

Title: EHS Specialist

Date: 9/13/2018 3:00:46 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
401762787	FIR RESOLUTION SUBMITTED
401762790	MD Radke 22-1 Photo

Total Attach: 2 Files