

Inspection Photos

Location Name: Canal 2 Location ID 318027

Inspection Date: 09/13/2018



Photo 1 – Excavation exposing groundwater at Canal 2 wellhead.



Photo 2 – Excavation exposing groundwater at Canal 2 wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Canal 2 Location ID 318027
Inspection Date: 09/13/2018



Photo 3 – One of several corroded dumphines.



Photo 4 – Corrosion hole in removed dumpline.



Inspection Photos

Location Name: Canal 2 Location ID 318027

Inspection Date: 09/13/2018



Photo 5 – Exposed dumpline trench.



Photo 6 – Excavation of dumplines at former tank battery in progress.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Canal 2 Location ID 318027

Inspection Date: 09/13/2018



Photo 7 – Excavation at former tank battery.



Photo 8 – Excavation exposing impacted soil at former tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Canal 2 Location ID 318027

Inspection Date: 09/13/2018



Photo 9 – Former produced water pit at Canal 2 tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources