

Inspection Photos  
Location Name: NVega 4B  
Location ID: 311764



**Photo 1: Wellhead sign. Nearest public access road missing.**



**Photo 2. Unmarked buckets at separators.**

Inspection Photos  
Location Name: NVega 4B  
Location ID: 311764



**Photo 3: Stained soil North of separators.**



**Photo 4. Manifold around perimeter of location.**