

Inspection Photos
Location Name: NVega 2A
Location ID: 334433



Photo 1: Conductors have been removed.




Photo 2. Nearest public access not listed on sign.