

Inspection Photos
Location Name: BCU 150 Pad
Location ID: 334554



Photo 1: Out of service tanks on location.



Photo 2: Out of service tanks on location.

Inspection Photos
Location Name: BCU 150 Pad
Location ID: 334554



Photo 3: Chemical storage tank has been put in containment. Labels are faded and not legible.



Photo 4. Risers from tank battery have not been removed.

Inspection Photos
Location Name: BCU 150 Pad
Location ID: 334554



Photo 5: Stained soil has been covered or removed.



Photo 6. Unused equipment has been removed.