

Inspection Photos

09/14/2018

Operator: DIVERSIFIED OPERATING
CORPORATION - 24461

Location ID: 409370

Inspection Doc. Number: 682503904
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the northeast corner of the location, facing south. Photos 1-3 provides an overview of the location, from south to west. Photos show that additional reclamation activities do not appear to have been conducted; location remains predominantly bare and exposed soil, gravel remains evident, recontouring/regrading does not appear to have been conducted.



Photo 2: Photo taken from the northeast corner of the location, facing southwest



Photo 3: Photo taken from the northeast corner of the location, facing west. Photo shows what appears to be a soil stockpile (berm).



Photo 4: Photo taken from the southwest corner of the location, facing northeast. Photo shows location remains predominantly bare and exposed soil. Unable to find evidence that additional reclamation activities have been conducted per the corrective actions



Photo 5: Photo taken from the south end of the location. Photo shows area where erosion degradation remains evident.



Photo 6: Photo taken from the center of the pad, facing west. Photo shows gravel/base has not been removed from the location.



Photo 7: Photo taken from the access road, east of the location. Photo shows access road has not been reclaimed.



Photo 8: Photo taken from the access road, east of the location facing west. Photo shows access road has not been reclaimed.



Photo 9: Photo taken from the access road, east of the location facing north. Photo shows access road has not been reclaimed. Photo also shows culvert has not been removed.