

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/17/2018

Submitted Date:

09/17/2018

Document Number:

692600340

FIELD INSPECTION FORM

Loc ID 303913 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10489
Name of Operator: AUGUSTUS ENERGY RESOURCES LLC
Address: 2016 GRAND AVENUE #A
City: BILLINGS State: MT Zip: 59102

Findings:

- 10 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 630-3909	greg.jones@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253789	WELL	PR	03/15/1996	GW	125-07667	WOOLERY-ROUNDTREE 11-34	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Two track through pasture		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to fence		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Metal panels around unit, wellhead and meter shed		
Corrective Action:			Date:
Type	LOCATION		
Comment:	Wire fence around entire location		
Corrective Action:			Date:

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Electric motor and telemetry equipment		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Weatherford unit		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator 50% buried by meter shed		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 253789 Type: WELL API Number: 125-07667 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT