

**Inspection Photo**  
**Jackson 15-28**  
**API # 045-07633**  
**Inspection # 689301929**



**Location Photo #1**

**Location Photo #2**

**Inspection Photo  
Jackson 15-28  
API # 045-07633  
Inspection # 689301929**



**Location Photo #3, Sediment being moved off location**

**Location Photo #4, Sediment being moved off location**

**Inspection Photo  
Jackson 15-28  
API # 045-07633  
Inspection # 689301929**



**Location Photo #5, Sediment being moved off location**

**Location Photo #6, Sediment being moved off location**

**Inspection Photo**  
**Jackson 15-28**  
**API # 045-07633**  
**Inspection # 689301929**



**Location Photo #7, Sediment being moved off location**

**Location Photo #8, Sediment being moved off location**

**Inspection Photo**  
**Jackson 15-28**  
**API # 045-07633**  
**Inspection # 689301929**



**Location Photo #9, Sediment being moved off location**