

Inspection Photos
Location Name: RURAL LAND 32-31 #2
Remediation: 10589



Photo 1. Monitoring wells- facing west, down gradient



Photo 2. Locked out/tagged out flowline risers

Inspection Photos
Location Name: RURAL LAND 32-31 #2
Remediation: 10589



Photo 3. Unused equipment on location from recently plugged and abandoned well



Photo 4. Concrete vault on location, Operator will need to file a Form 27 for removal.

Inspection Photos
Location Name: RURAL LAND 32-31 #2
Remediation: 10589



**Photo 5. Monitoring wells on location, photo looking east,
up gradient**