

Inspection Photos
Location Name: JILLSON A #1
Location ID: 240989



PHOTO #1: WELLHEAD



PHOTO #2: TANK BATTERY/WEEDS INSIDE BERMES



Inspection Photos
Location Name: JILLSON A #1
Location ID: 240989



PHOTO #3: WEEDS ALL AROUND HEATED TREADER INSIDE AND OUTSIDE BERMS

PHOTO #4: WEEDS ALL AROUND PRODUCED WATER TANK INSIDE AND OUTSIDE BERMS

Inspection Photos
Location Name: JILLSON A #1
Location ID: 240989



**PHOTO #5: HOLE IN OPEN TOP PRODUCED WATER TANK
WILDLIFE PROTECTION SCREEN**

PHOTO #6: STAINED SOIL INSIDE COMPRESSOR HOUSE

Inspection Photos
Location Name: JILLSON A #1
Location ID: 240989



PHOTO #7: WEEDS AROUND ECD

PHOTO #8: MORE PHOTOS OF WEEDS AROUND LOCATION

Inspection Photos
Location Name: JILLSON A #1
Location ID: 240989



PHOTO #9: WEEDS AROUND LOCATION

PHOTO #10: MORE WEEDS