

Inspection Photo
Savage 1-22
API # 045-07184
Inspection # 689301945



Location Photo #1



**Location Photo #2, debris on location,
southwest side.**

Inspection Photo
Savage 1-22
API # 045-07184
Inspection # 689301945



**Location Photo #3, debris on location,
southwest side.**



**Location Photo #4, debris on location,
southwest side.**

Inspection Photo
Savage 1-22
API # 045-07184
Inspection # 689301945



**Location Photo #5, debris on location,
southwest side.**



**Location Photo #6, Heavy erosion along
access road**

Inspection Photo
Savage 1-22
API # 045-07184
Inspection # 689301945



**Location Photo #7, Heavy erosion along
access road.**