

Inspection Photo
Savage 1-42
API # 045-07185
Inspection # 689301949



Location Photo #1



**Location Photo #2, unmarked deadman
anchor in grass, NW corner.**

Inspection Photo
Savage 1-42
API # 045-07185
Inspection # 689301949



Location Photo #3, unmarked deadman near tanks.