

Inspection Photos

Operator: BENSON-MONTIN-GREER DRILLING

API: 05-067-05805

Date: 9/13/2018



Photo 1. View of the reclaimed access road from the beginning of the road. Road closure is in accordance with final reclamation rules.



Photo 2. View of the eastern project area from the southwestern corner facing center. Well pad and access road are recontoured, straw mulched, and seeded with grasses. Species identification was not apparent at the time of the inspection.



Photo 3. View of the northern project area from the northwestern edge facing eastward.



Photo 4. View of germination sampling “Quadrat 1”, along the access road.




Photo 5. View of germination sampling “Quadrat 2”, along the access road.