

Inspection Photos

Location Name: Sooner Unit - 68N58W / 28SENW

Location #: 330480



Photo #1

Sooner Unit 28-6-1 (API # 05-123-19173) wellhead

Bradenhead NOT plumbed to surface

Stained soil

Unused equipment



Photo #2

Sooner Unit 28-6-1 wellsite

New well sign



Inspection Photos

Location Name: Sooner Unit - 68N58W / 28SENW

Location #: 330480



Photo #3

Sooner Unit Battery

