

Inspection Photos

Location Name: Sooner Unit - 68N58W / 21NWNW

Location #: 323773



Photo #1

Sooner Unit 4-21 (API # 05-123-13505) wellhead

Bradenhead NOT plumbed to surface

Stained soil

Unused Equipment



Photo #2

Sooner Unit 4-21 wellsite

New sign



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sooner Unit - 68N58W / 21NWNW

Location #: 323773



Photo #3

Sooner Unit Battery

