

Inspection Photos

Operator: QEP Energy

API: 05-033-06114

Date: 9/18/2018



Photo 1. View of the project area from the northern edge facing center.



Photo 2. View of the northern portion of the project area from the northeastern edge facing westward.



Photo 3. View of the eastern portion of the project area from the northern edge facing southeastward.



Photo 4. View of the western project area from the northwestern corner facing southward.



Photo 5. Pit in the eastern project area. Not apparent whether this is still in use.



Photo 6. View of surrounding vegetation from the access road edge facing southwestward. Vegetation is comprised of weedy annual grassy and forbs such as cheatgrass (*Bromus tectorum*) and yellow tumbledustard (*Sysimbrium* sp.) as well as native rubber rabbitbrush (*Chrysothamnus nauseosus*).