

Inspection Photos

Loc#447512

Operator: Sandridge

Inspection Number: 692400134

Inspection Date: 9/14/2018





Photo#1:
Overview of Location from entry to Northeast.

September 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Open Range Loc#447512



Photo#2: 10/24/17

One section of rutting (noted in Previous CI Insp) at SE corner of Location, where it appears heavy equipment has exited Location through wire gate has not been addressed. Annual weeds have also taken advantage of the Disturbance.

Photo#3: 9/14/18

September14, 2018



Photo#4: 10/24/17

Overall site is in much improved condition from previous Construction Insp.



Photo#5: 9/14/18

September 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Open Range Loc#447512



Photo#6:
Straw wattles / bales have been broken up, but not scattered very efficiently.

September14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Open Range Loc#447512