

## Inspection Photos

Location Name: Peters - 612N61W / 33SESE

Location #: 317545



Colorado Oil & Gas Conservation Commission  
40.9601, -104.20309, 1580.0m, 278°  
2018/09/20 01:35:56 PM

**Photo #1**

**Peters 01** (API # 05-123-07170) wellhead



Colorado Oil & Gas Conservation Commission  
40.95816, -104.20392, 1545.0m, 85°  
2018/09/20 01:52:00 PM

**Photo #2**

**Peters 1 & 3** Battery



**Inspection Photos**  
**Location Name: Peters - 612N61W / 33SESE**  
**Location #: 317545**



**Photo #3**  
**Peters 1 wellsite sign**



**Photo #4**  
**Peters 1 Gas engine**  
**Stained soil near engine base**

**Inspection Photos**  
**Location Name: Peters - 612N61W / 33SESE**  
**Location #: 317545**



**Photo #5**  
**Peters 1 Gas engine**  
**Stained soil near engine base**



**Photo #6**  
**Peters 1 Gas engine**  
**Stained soil exhaust area**

**Inspection Photos**  
**Location Name: Peters - 612N61W / 33SESE**  
**Location #: 317545**



Colorado Oil & Gas Conservation Commission  
40.95834, -104.20366, 1574.0m, 354°  
2018/09/20 01:52:22 PM

**Photo #7**  
**Peters 1 & 3 Battery sign**  
**Peters 2 has been P&A'd**  
**Sign needs updated**



Colorado Oil & Gas Conservation Commission  
40.9584, -104.20367, 1576.0m, 356°  
2018/09/20 01:52:42 PM

**Photo #8**  
**Peters 1 & 3 H2O vault**  
**Capacity not legible**

**Inspection Photos**  
**Location Name: Peters - 612N61W / 33SESE**  
**Location #: 317545**



**Photo #9**  
**Peters 1 & 3 Produced H2O tank**  
**Contents – Capacity Not posted**  
*From previous FIR*



**Photo #10**  
**Peters 1 & 3 Battery tanks**  
**Contents, Capacity, Placards posted**

## Inspection Photos

Location Name: Peters - 612N61W / 33SESE

Location #: 317545



**Photo #11**

**Peters 1 & 3 Berms**  
**Low berms at loadout**  
*From previous FIR*



**Photo #12**

**Peters 1 & 3 Battery tanks**  
**Berms - Adequate**

