

Inspection Photos
Location Name: Iles Dome Unit 25
API: 05-081-05086



Photo 1. Overview of location taken at entrance facing southwest.

Inspection Photos
Location Name: Iles Dome Unit 25
API: 05-081-05086



Photo 2. Cellar full of fluid.



Photo 3. Close up of fluid in cellar.